## **USB-C** COMPARISON CHART



In order to help users navigate their way around the different cables available today, we have created the '5-star' criteria system to rate and classify cables in line with the 5 most crucial operational aspects. On this page, you can find a short explanation of these criteria as well as what the corresponding star levels mean for each, and further on you can find our Comparison Chart including a wide range of cables and how they performed during our tests against these 5 criteria.

	P		ss-				
<b>5 Criteria</b> 5 Stars	<b>4K 60FPS Video</b> and Audio 4-Lane DisplayPort Alt mode	Mouse, Keyboard, Speakerphone, Thumb Drive and Webcam USB 2.0 480 Mbps "High Speed"	<b>4K Webcam, SSD storage</b> USB 3 Gen1 5 Gbps "SuperSpeed"	<b>Fast Charging of Laptops,</b> <b>Tablets and Phones</b> 60W / 3 A charging and eMarker	<b>Convenient to use</b> <b>and to install</b> Connector dimensions according to standard; No bulky repeaters along the cable		
*	<ul> <li>Up to 4K60 (4-Lane DP)</li> </ul>	<ul> <li>Stable with all host</li> </ul>	<ul><li>Stable with all hosts</li><li>All wires are present</li></ul>	<ul> <li>At least 60 W PD support <b>AND</b></li> <li>Proper eMarker</li> </ul>	<ul> <li>Convenient to use and to install (No design flaws)</li> </ul>		
*	<ul> <li>Up to 4K30 (2-Lane DP)</li> </ul>	<ul> <li>Unstable with some hosts</li> </ul>	<ul> <li>Unstable with some hosts</li> </ul>	<ul> <li>PD supports less than 60W <b>OR</b></li> <li>Missing eMarker</li> </ul>	<ul> <li>At least one design flaw</li> </ul>		
	No support	<ul><li>No support</li><li>Missing wires</li></ul>	<ul><li>No support</li><li>Missing wires</li></ul>	<ul><li>No PD support</li><li>No eMarker</li></ul>	<ul> <li>Multiple design flaws</li> </ul>		

	ommended Cables aurus UCX Products	Most Important						Least Important		
-	-C to USB-C)	Length	Category	4K60 Video	USB 2.0	USB 3.X	Charging + eMarker	Conve- nience	Comments	Rating
	Lightware CAB-USBC-T100A	1m	Copper	*	*	*	*	*		****
	Sommer HI-U4CC-0100	1m	Copper	*	*	*	*	*		****
	Lightware CAB-USBC-T200C	2m	Copper	*	*	*	*	*		****
	Apple Thunderbolt 4 Pro	1,8m/3m	Active Copper	*	*	*	*	*		****
	Apple Thunderbolt 3 Pro	2m	Active Copper	*	*	*	*	*		****
	TrippLite U420-006-5A	1,8 m	Copper	*	*	*	*	*	Rigid cable	****
	Lightware CAB-USBC-T200A/T300A	2m/3m	Copper	*	*	*	*	*	Only 60W charging power supported	****
Recommended for Taurus UCX	Lightware CAB-USBC-T400B/500B	4m/5m	Copper (Microcoax)	*	*	*	*	*	Only 60W charging power supported	****
r Tau	Atlona AT-LC-UC2UC-2M	2m	Copper	*	*	*	*	*	Only 60W charging power supported	*****
ed for	Freeport 26-715-06 (Extron)	1,8m	Copper	*	*	*	*	*	Only 60W charging power supported	*****
nend	<b>Delock</b> 83668	2m	Copper	*	*	*	*	1	Only 60W charging power supported; Rigid cable	****
Recomn	Vivolink PROUSBCMM3	3m	Copper	*	*	*	*	*	Only 60W charging power supported	*****
	CableWholesale 10U4-32006	1,8m	Copper	*	*	*	☆	*	Only 30W charging power supported	****
	Comprehensive USB3-CC-10SP	3m	Copper	*	*	*	☆	*	Only 15W charging power supported	****
	CableWholesale 10U4-32010	3m	Copper	*	*	*	☆	*	Only 30W charging power supported	****
	FSR LP-TBRT-5-USBC-USBC	5m	Copper	*	*	*	☆	*	Only 30W charging power supported	****
	Kramer CA-U32/FF-10	3m	Copper	*	*	*	*		Only 60W charging power supported; Rigid cable	****
	Lightware CAB-USBC-AOC800K/AOC1000K	8m/10m	Active Optical			*	*	*	Only 4K30 video (2-lane DP Alt mode) supported; 2 Tier added at the USB2.0 topology; Active optical cable with specific direction;	****
	<b>TTL-Taiwan</b> 20105	2m	Copper	*	*	*	☆	1	eMarker chip cannot be read; bigger cable head	****

Recommended Cables for Taurus UCX Products(USB-C to USB-C)Length			Most Important						Least Important	
		Length	Category	4K60 Video	USB 2.0	USB 3.X	Charging + eMarker	Conve- nience	Comments	Rating
	Vivolink PROUSBCMM4	4m	Copper	*	*	*	*	*	USB2.0 lines does not work with some tested laptops*; only 60W charging power supported	****
	Bizlink KSC001R-16X	4m	Active Copper	1	*	*	*	*	Only 4K30 video (2-lane DP Alt mode) supported; only 60W charging power supported; Active copper cable with specific direction;	
	Extron USBC Pro/30	9,1m	Active Optical	*	*	*	*		Only 4K30 video (2-lane DP Alt mode) supported; 2 Tier added at the USB2.0 topology, not recommended for complex USB systems	
	Tether Tools CUC15	4,6m	Copper	*	*	*	☆	*	USB2.0 and USB3 lines does not work with some tested laptops*; only 30W charging power supported	***
At your own risk	Vivolink PROUSBCMM5	5m	Copper	*	*	*	☆	*	USB2.0 and USB3 lines does not work with some tested laptops*; only 30W charging power supported	***
	<b>M-CAB</b> 2200046	3m	Copper	*	*	*	☆		USB2.0 and USB3 lines does not work with some tested laptops*; Missing E-marker	***
	Freeport KFCB201208	4,5m	Copper	*	*	*	☆	1	USB2.0 and USB3 lines does not work with some tested laptops*; only 30W charging power supported	***
	Newnex U4SLC01C01-050	5m	Copper	*	*	*	☆	1	USB2.0 and USB3 lines does not work with some tested laptops*; Missing E-marker	***
	Kramer CLS-AOCU32/FF-35	10,7m	Active Optical	*		*	☆	*	Only 4K30 video (2-lane DP Alt mode) supported; USB2.0 lines does not work with some tested laptops*; only 30W charging power supported;	
	Purelink FX-I600-010	10m	Active Optical			*	☆	*	Only 4K30 video (2-lane DP Alt mode) supported; 2 Tier added at the USB2.0 topology, not recommended for complex USB systems; only 30W charging power supported	***
	Cosemi 175USH31CCMM015M001	15m	Active Optical	*	*	☆	☆	☆	DP Alt mode only (no USB3 data); only 30W charging power supported	**

\*Tested hosts: Lenovo ThinkPad X280 Laptop; Dell G5 5587 Laptop. **These results were** experienced with Lightware Taurus UCX product, your experience may vary.

Recommended Cables for Taurus UCX Products (USB-C to USB-C)			Most Important				Least Important			
		Length	Category	4K60 Video	USB 2.0	USB 3.X	Charging + eMarker	Conve- nience	Comments	Rating
NCX	iiglo II-USBAMUSBC30-B300	3m	Copper	*	*		☆	*	USB3 lines does not work with some tested laptops*; only 30W charging power supported; Failed Total phase "Eye pattern" instrument test	****
n sn	<b>Club3D</b> CAC-1535	5 m	Active Copper	*	☆	☆	*	1	4 Iane DP Alt mode only (no USB3 and no USB2.0 data)	**
ır Taurus	<b>HP</b> 9JH45AA	5 m	Active Copper	*		☆	☆	1	4 Iane DP Alt mode only (no USB3 data); USB2.0 lines does not work with some tested laptops*; only 15W charging power supported	**
ded fo	Cable Matters 201034-BLK-5m	5 m	Active Copper	*	*		☆	☆	USB2.0 and USB3 lines does not work with some tested laptops*; only 30W charging power supported; Amplifier in the middle	**
Not recommended for	Newnex ULK10G-CC-8M	8 m	Active Copper	*			☆	☆	USB2.0 and USB3 lines does not work with some tested laptops*; only 30W charging power supported; Repeater in the middle, and quite rigid	
	SmartAVLink SCVC-3100-20	20 m	Active Optical	*	☆	☆	☆	☆	4 lane DP Alt mode only (no USB3 and no USB2.0 data); No charging power	*
	<b>Club3D</b> CAC-1589	20 m	Active Optical	*	☆	☆	☆	☆	4 Iane DP Alt mode only (no USB3 and no USB2.0 data); No charging power	*
No Video with Taurus UCX	SmartAVLink KUCC-3100-020	2 m	Copper	☆	*	*	☆	*	No Video and Audio due to missing SuperSpeed wires; only 30W charging power supported	***
	Apple USB-C charge cable	1 m / 2m	Copper	☆	*	☆	*	*	No Video and Audio due to missing SuperSpeed wires; For charging only	***
	Belkin Thunderbolt 3	2m	Active Copper		*	☆	*	*	No DP Alt mode and no USB3 data supported, therefore video and audio signals won't be transmitted for Taurus UCX;	***
	Lanberg CA-CMCM-31CU-0030-BK	3m	Copper			*	☆	*	No USB3 lines for video; only 15W charging power supported; USB2.0 lines does not work with some tested laptops*	**

Cables that don't support video transmission are **not** 'host cables' by Lightware's definition!

\*Tested hosts: Lenovo ThinkPad X280 Laptop; Dell G5 5587 Laptop. **These results were experienced with Lightware Taurus UCX product, your experience may vary.**